

DATE

TO :

FROM :

ACTION:

INFO :

1	9
2	10
3	11
4	12
5	13
6	14
7	15
8	16

OKS 1-10 Sg

IN 55636

TO

INFO

CITE

T O P S E C R E T 150600Z CITE [REDACTED] 7324 25X1A

IMMEDIATE [REDACTED] INFO [REDACTED] 25X1A 25X1A

25X1A

25X1A

REF: [REDACTED] 0052

1. AIRCRAFT BEING CHECKED NOW TO DETERMINE ACTUAL HF OR BW PROBLEM. ANTICIPATE NOT MORE THAN 6 HOURS TO REPAIR OR REPLACE ENTIRE SYSTEM.

2. PILOT AND AIRCRAFT WISE WE SHOULD BE ABLE TO LAUNCH SAME 25X1C OR MODIFIED MISSION ON 16 MAY, IF DESIRED [REDACTED] AGREES.

3. STANDING BY FOR INSTRUCTIONS.

T O P S E C R E T TOR 0614Z 15 MAY 66

